

# JIS Standards prepared by APPIE

NO	Std's NO	Title
1	JISZ8801-1:2006	Test sieves -- Part 1: Test sieves of metal wire cloth
2	JISZ8801-2:2000	Test sieves -- Part 2: Test sieves of perforated metal plate
3	JIS Z 8801-3:2000	Test sieves -- Part 3: Test sieves of electroformed sheets
4	JIS Z 8815:1994	Test sieving -- General requirements
5	JIS Z 8816:2001	Particulate materials - General requirements for methods of sampling
6	JIS Z 8817:2002	Test method for explosion pressure and rate of pressure rise of combustible dusts
7	JIS Z 8818:2002	Test method for minimum explosible concentration of combustible dusts
8	JIS Z 8819-1:1999	Representation of results of particle size analysis -- Part 1: Graphical representation
9	JIS Z 8819-2:2001	Representation of results of particle size analysis -- Part 2: Calculation of average particle sizes/diameters and moments from particle size distributions
10	JIS Z 8820-1:2002	Determination of particle size distribution by gravitational liquid sedimentation methods -- Part 1: General principles and guidelines
11	JIS Z 8820-2:2004	Determination of particle size distribution by gravitational liquid sedimentation methods -- Part 2: Fixed pipette method
12	JIS Z 8822:2001	Determination of particle size distribution by the mass of sediment-particles in liquid
13	JIS Z 8823-1:2001	Determination of particle size distribution by centrifugal liquid sedimentation methods -- Part 1: General principles and guidelines
14	JIS Z 8823-2:2004	Determination of particle size distribution by centrifugal liquid sedimentation methods -- Part 2: Photocentrifuge method
15	JIS Z 8824:2004	Sample preparation -- Dispersing procedures for powders in liquids
16	JIS Z 8825-1:2001	Particle size analysis -- Laser diffraction methods -- Part 1: General principles
17	JIS Z 8826:2005	Particle size analysis -- Photon correlation spectroscopy
18	JIS Z 8830:2001	Determination of the specific surface area of powders (solids) by gas adsorption method
19	JIS Z 8840:1993	Powder processing machinery and equipment -- Graphical symbols
20	JIS Z 8841:1993	Granules and agglomerates -- Test methods for strength
21	JIS Z 8842:1998	Instrumentation symbols for powder processes
22	JIS Z 8843:1998	Industrial plate screens
23	JIS Z 8901:2006	Test powders and test particles
24	JIS Z 8908:1998	Filter fabrics for dust collection
25	JIS Z 8909-1:2005	Test method of filter media for dust collection Part 1: Filter efficiency
26	JIS Z 8910:2007	Test method of filter media for dust collection -- Sampling and test method for fabric filter durability